## State of Canfornia — The mesources Agency DEPARTMENT OF PARKS AND RECREATION

## HISTORIC RESOURCES INVENTORY

			S	er. No				
HABS_		_HAER	Loc	SHL!	۷o	NF	Status	30
UTM:	Α	10/627	396.409	6504	C	:	· · -	
	_							

	Common name:						
2.	Historic name: _			·			
3.	Street or rural ac	ddress:	7453	Monterey	Street	21.	
	City Gilro	ıy		Zip	95020	County_Sant	ca Clara
4.	Parcel number:	7990	<u> </u>				
5.	Present Owner:	Bonnie Brown				Address: <u>799</u>	Claremont Dr.
	City Morgan	Hill, CA		Zip <u>95037</u>	Ownersh	ip is: Public	Private X
6.	Present Use:	Retail/Comme	ercial	Orio	ginal use:	Retail/Commer	cial

## DESCRIPTION

- 7a. Architectural style: Commercial - Mediterranean
- 7b. Briefly describe the present physical appearance of the site or structure and describe any major alterations from its original condition:

Another well-scaled brick commercial building from the 1920's which has unfortunately been altered by the stuccoing over of the street front commercial window forms. The structure is rectangular in plan. The facade is flat faced with a slightly projected cornice line, a projecting string course, decorative paneling on the upper portion of the street facade. A band of horizontal shaped windows separates the stucco surface from the area that contains the front windows. Note, however, that the existing fenestration is an altered form from the original large plate glass which typifies the commercial style and may be seen unaltered at #7357 next door. The entry is recessed and marked by a simple wooden door which is also an alteration. The major detail element is found in the decorative tile work which frames the lower facade and which is found in slight variations.



5.	Estimated Factual Factual
<b>)</b> .	Architect Unknown
Ō.·	Builder Unknown
1.	Approx. property size (in feet) Frontage 22 Depth 140

Date(s) of enclosed photograph(s) Mar. 1986

13.	Condition: ExcellentGood _AFair Deteriorated No longer in existence
14.	Alterations: Facade Covered in stucco
15.	Surroundings: (Check more than one if necessary) Open landScattered buildings Densely built-up _X Residential Industrial CommercialX. Other:
16.	Threats to site: None known X Private development Zoning Vandalism Public Works project Other:
17.	Is the structure: On its original site? X Moved? Unknown?
18.	Related features:
SIG1 19.	NIFICANCE  Briefly state historical and/or architectural importance (include dates, events, and persons associated with the site.)
	This well formed structure type is the basis for understanding downtown Gilroy. The sum of these buildings is greater than the individual value of each. Downtown Gilroy would be enhanced by appropriate rehabilitation of this structure, however, its removal would cause irreparable damage to the distinctiveness that creates downtown Gilroy.  The businesses in this commercial retail structure have included Oliveira's Brownbuilt Shoes, 1926 through 1930. Before that, Oliveira's was known for boots and saddles.
20.	Main theme of the historic resource: (If more than one is checked, number in order of importance.)  Architecture Arts & Leisure Economic/Industrial Exploration/Settlement Military Religion Social/Education
21.	Sources (List books, documents, surveys, personal interviews and their dates).
	American Architecture Since 1780, Whiffen
	Sanborn Maps 1888, 1892, 1906, 1926
22.	Gilroy Museum File - Monterey Street  April 1986  By (name) The Firm of  Organization BONNIE L. BAMBURG  Address: 247 N. Third Street  City San JOse, CA Zip 95112  Phone: (408) 971-1421

Phone: \_