

HISTORIC RESOURCES INVENTORY

Ser. No. \_\_\_\_\_  
HABS \_\_\_\_\_ HAER \_\_\_\_\_ Loc \_\_\_\_\_ SHL No. \_\_\_\_\_ NR Status 5D  
UTM: A 10/627091.4096929 C \_\_\_\_\_  
B \_\_\_\_\_ D \_\_\_\_\_

IDENTIFICATION

1. Common name: \_\_\_\_\_
2. Historic name: \_\_\_\_\_
3. Street or rural address: 7725 Eigleberry Street  
City Gilroy Zip 95020 County Santa Clara
4. Parcel number: 79900331
5. Present Owner: Louise Weske Address: 7751 Eigleberry S  
City Gilroy Zip 95020 Ownership is: Public \_\_\_\_\_ Private X
6. Present Use: Residence Original use: Residence

DESCRIPTION

- 7a. Architectural style: Early Craftsman
- 7b. Briefly describe the present *physical appearance* of the site or structure and describe any major alterations from its original condition:

The medium gable is highlighted by some lattice-work decoration at the top of this example of an early craftsman style house. The rafters are exposed at the eaves and there are large, exposed support brackets above the clapboard siding. The recessed porch has square pillars and there is some stained glass in the front door.



8. Construction date:  
Estimated 1916 Factual \_\_\_\_\_
9. Architect \_\_\_\_\_  
Unknown
10. Builder \_\_\_\_\_  
Unknown
11. Approx. property size (in feet)  
Frontage 40 Depth 150  
or approx. acreage \_\_\_\_\_
12. Date(s) of enclosed photograph(s)  
Mar. 1985

13. Condition: Excellent \_\_\_ Good X Fair \_\_\_ Deteriorated \_\_\_ No longer in existence \_\_\_
14. Alterations: \_\_\_\_\_
15. Surroundings: (Check more than one if necessary) Open land \_\_\_ Scattered buildings \_\_\_ Densely built-up X  
Residential X Industrial \_\_\_ Commercial \_\_\_ Other: \_\_\_\_\_
16. Threats to site: None known X Private development \_\_\_ Zoning \_\_\_ Vandalism \_\_\_  
Public Works project \_\_\_ Other: \_\_\_\_\_
17. Is the structure: On its original site? X Moved? \_\_\_ Unknown? \_\_\_
18. Related features: Large trees

**SIGNIFICANCE**

19. Briefly state historical and/or architectural importance (include dates, events, and persons associated with the site.)

This early craftsman style house is in excellent condition today and reflects the care of construction at the time it was built. The latticwork decorations shows the attention to detail given the this early Gilroy home. Its emphasis on the use of natural materials points out the casual relationship with the art of doors.

20. Main theme of the historic resource: (If more than one is checked, number in order of importance.)  
Architecture 1 Arts & Leisure \_\_\_\_\_  
Economic/Industrial \_\_\_ Exploration/Settlement \_\_\_\_\_  
Government \_\_\_ Military \_\_\_\_\_  
Religion \_\_\_ Social/Education \_\_\_\_\_

21. Sources (List books, documents, surveys, personal interviews and their dates).

A Field Guide to American Houses  
McAlister

Sanborn Map 1888,1908

22. Date form prepared April 1986  
By (name) The Firm of  
Organization BONNIE L. BAMBURG  
Address: 247 N. Third Street  
City San Jose, CA Zip 95112  
Phone: (408) 971-1421

Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):

